

ONPOINT

General Labors – 100 positions. (1-day unpaid training-Hands on Assessment)

General Laborers to perform general facility maintenance duties within a refinery or petrochemical facility. These duties include, but are not limited to: General clean up/trash pick-up and disposal; water distribution within the facility; unit clean-up and removal of waste; and cooling tower clean-up and small/light construction projects (uses of hand tools). . Other duties and responsibilities may be assigned.

Safety Attendants – 50 positions (1-day unpaid training-Hands on Assessment)

Hole Watch - Stationed outside of a confined area in order to prevent coworkers from safety incidents. Position must be alert and dependable at all times.

Fire Watch - Implement and ensure fire-safety of a building or area in the event of any act e.g. hot work or situation instigating an increased fire risk. Position must be alert and dependable at all times.

Bottle Watch - Stationed near air gauges while coworkers work under fresh breathing air. Replaces air when needed. Position must be alert and dependable at all times.

Requirements:

Must possess a valid, active TWIC Card

Must pass a strict background check

Must pass a pre-employment DISA drug/alcohol test

May be required to pass a respirator fit test (depending on the facility)

Must have reliable transportation

Must have lace-up, ankle high, steel-toed boots **MUST HAVE FOR HANDS ON ASSESSMENT**

Must possess a valid driver's license (Class C Standard) with a clean driving record

Candidates are expected to commute to different work site as needed

May be required to operate a forklift

Physical Requirements:

Walk up to 3 miles per day in the elements (excessive heat, cold, humidity, etc.)

Must be able to lift up to 50 lbs. repetitively

Bend, stretch, twist, or reach out with the body, arms, and/or legs including climbing in pipe racks

Climbing stairs and/or ladders and work at high elevations at times (up to 300 ft.)

Kneeling, crawling, pushing and pulling

Walking around on uneven, slick, or rocky surfaces

Must be willing and able to work extended hours (up to 12 hour shifts, 7 days per week)

EDUCATION & EXPERIENCE:

High School Diploma or GED

1-3 months prior experience as a General Labor/Firewatch/Holewatch/Bottlewatch preferred.

Prior experience working in a refinery or petrochemical facility preferred.

All applicants must apply online prior to interview. www.onpoint-us.com click Careers, select Safety, Logistics & Ventilation Positions, then select either General Labor or Safety Attendant to apply. Or Scan QR Code below.

